| ∢Work Order | ID | 60744 |
|--------------------|------|------------|
| Thursday, July 22, | 2010 | 8:17:59 AM |

Page 1

Item ID:

D205-634-041

Accept

Setup Start

Stop



Revision ID:

Item Name:

Replacement Skidtube

Start Date:

7/21/2010

Start Oty: 1.00

Required Date: 8/6/2010

Req'd Qty: 1.00



Cust Item ID: Customer:

Reference:

Approvals:

Process Plan:

QC:

Date: 10-7-

2/ Tooling: SPC (Y/N):

Date:

Date:

Run

Start



Stop

Sequence ID/

Operation Description

Date:

Set Up/ **Run Hours** **Tool ID**

Tool # Plan Code Qty

Reject Accept Qty

Reject Number

Insp. Stamp

Work Center ID Draw Nbr

Revision Nbr

D2580

Rev D

DOCUMENT CONTROL

Memo

0.00

0.00

CZ 10/8/12

Document Control

Photocopy D205-634 bluefile & type labels per PPP D205-634-041 CHG002

110

CNC Bend 1

BENDING MACHINE - SKIDTUBES

Memo

0.00

0.00

CNC Delta 100 Bender

1-Bend as per program D2580.C on CNC Bender and Folio 16

2-Cut tubes as per Dwg. D2580

3- scribe batch# in aft end of tube



| Dart Ae | rospace | e Ltd | | | | | | * * | | |
|-----------|---------|-------------------|------------------------------|------------------------------|--------------|-------|---------|-------------------------------------|--------------------------|--|
| W/O: | | | V | WORK ORDER CHANGES | | | | γ • • | | |
| DATE STEP | | PRO | PROCEDURE CHANGE | | | Date | ate Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| Part No | : | PAR #: | Fault Ca | tegory: No | CR: Yes | No DC | A: | _ Date: _ | | |
| | R | esolution: | Disposition: QA: N/C Closed: | | | | | Date: _ | | |
| NCR: | | V | VORK OR | DER NON-CONFORMANC | E (NC | R) | | | | |
| | | Description of NC | | Corrective Action Section B | | Verif | ication | Approval | Approval | |
| DATE | STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign Date | & Sec | | Chief Eng | QC Inspector | |
| | | | | | | | | | | |
| · | | | | | į | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Work Order ID 60744



Page 2

Thursday, July 22, 2010 8:17:59 AM

Item ID:

D205-634-041

Accept



Setup Start



Revision ID:

Item Name:

Replacement Skidtube

Start Date:

7/21/2010

Start Qty: 1.00

Req'd Qty: 1.00



Cust Item ID:

Customer:

Tool ID

Reference:

Approvals:

Required Date: 8/6/2010

QC:

Process Plan:

Operation

Description

Date:_____

Date: _____ Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Tool # Plan

Start

Run

Accept

Qty

Stop



Reject

Number

Stop

Reject

Qty

Insp.

Stamp

Sequence ID/ **Work Center ID**

120

Skidtubes

Skidtubes

Memo

1- Deburr ends

QC5- Inspect part completeness to step on W/O

3- Prepare tube for welding, remove alodine as required.

0.00

0.00

2- C'sink holes as per dwg without cutting fluid

4- Scribe batch number insied aft end of tube.

Code

130

QC

Quality Control

Memo

0.00

0.00

Dart Aerospace Ltd

| W/O: | | WORK ORDER C | WORK ORDER CHANGES | | | | |
|------|------|------------------|--------------------|------|-----|-------------------------------------|-------------------------|
| DATE | STEP | PROCEDURE CHANGE | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approva QC Inspector |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

Part No: Das - 634-641 PAR #: ____ Fault Category: Skid ble NCR: Fes No DQA;

₽ Date: 1008.07

Resolution: Accepted Disposition: Use AS is. QA: N/C Closed:

| NCR: 6 | 444 | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | | | |
|-----------|-------|----------------------------------|----------------------|---|------|--------------|---------------------|--------------|--|--|
| | T` | Description of NC | | Corrective Action Section B | | Verification | Approval | Approval | | |
| DATE STEP | | Section A | Initial Chief Eng | Eng Chief Eng | | Section C | Chief Eng | QC Inspector | | |
| to about | | AFT HEIGHT 15 1.375 | CP. | varify cut clims as much as possible prior to chapping. | W) | | g. | | | |
| 1908/09 | 110-2 | ISTANCE FROM HET END TO | 10.00.09 | varily cut dims as much | 289 | 8 | 10.08.05 QS) 042 | 100809 | | |
| | | R.C. Benching | 951412 | As possible prior to chapping. | 1000 | 10/08/05 | 95) 042 | 10080 | | |
| | | 9 | | | | | , | | | |
| | | | | | | | | | | |
| | | | | · • • • • • • • • • • • • • • • • • • • | | | | | | |
| | | | | | , | | | | | |
| | | | | | | | | | | |
| | | | , | | | | | | | |
| | | | | | | | | | | |

Work Order ID 60744

Thursday, July 22, 2010 8:17:59 AM



Page 3

Item ID: D205-634-041 **Revision ID:**

Required Date: 8/6/2010

Accept



Setup Start



Item Name:

Replacement Skidtube

Start Date:

7/21/2010

Start Oty: 1.00

Req'd Oty: 1.00



Cust Item ID: Customer:

Tool ID

Reference:

| Approvals: | |
|------------|--|
|------------|--|

QC:

Process Plan:

Operation

Description

Date:

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date: Date:

Tool # Plan

Code

Run

Accept

Qty

Stop

Reject

Qty



Insp.

Stamp

Reject

Number

Sequence ID/ Work Center ID

140



Skidtubes Skidtubes

Memo

0.00

0.00

1-Weld step D2576 as per Dwg. D2580 and QSI 004

Date:_____

A/R□□□ Aluminum Rod

2-Prep per QSI 005 and weld crossbolt spacers D2579 as per Dwg, D2580, QSI

A/R□□□ Aluminum Rod

For D2579 spacers, weld one side, pass 3/8" drill, weld other side, pass 3/8" drill M114242

3-Grind welds as per Dwg D2580 Grind flush ridge made from bending

4-Drill holes for wearplates using DT 8217 & DT8937 Open holes to 19/64", adjust stopper not to hit web.Deburr

5-Counterbore crossbolt spacers to 7/16" ID x 1.0" deep as per Dwg D2580. Deburr holes

6-Drill pilot holes for aft cap using DT 8215Open holes to 0.208". Deburr

7-Drill pilot holes for Tow ring using DT8091, open to .640" and Deburr

| W/O: WORK ORDER CHANGES DATE STEP PROCEDURE CHANGE By Date Qty Approach Chief Er Proof M | Approvai |
|--|----------|
| DATE STEP PROCEDURE CHANGE By Date Qty Chief Er | Approvai |
| | |
| | |
| | |
| | |
| Part No: PAR #: Fault Category: NCR: Yes No DQA: Date | |
| Resolution: Disposition: QA: N/C Closed: Date | |
| NCR: WORK ORDER NON-CONFORMANCE (NCR) | |
| DATE STEP Description of NC Section A Corrective Action Section B Verification Section C Chief Eng Chief E | |
| | |
| | |
| | |

Work Order ID 60744

Thursday, July 22, 2010 8:17:59 AM



Page 4

Item ID:

D205-634-041

Accept

Setup Start

Revision ID:

Item Name:

Required Date: 8/6/2010

Replacement Skidtube

Start Date:

7/21/2010

Start Qty: 1.00

Req'd Qty: 1.00

Date:

Cust Item ID:

Customer:

Tool ID

Reference:

Approvals:

Process Plan:

Date:_____

Tooling:

SPC (Y/N):

Date:

Date:

Tool # Plan

Code

Start

Run

Stop

Reject

Number

Stop

Reject

Qty

Insp.

Stamp

Sequence ID/ **Work Center ID**

150

Quality Control

Operation **Description**

QC10- Inspect visual per QSI004- ground welds

Set Up/ **Run Hours**

0.00

Memo

160

QC Quality Control OC5- Inspect part completeness to step on W/O

0.00

Accept

Qty

170

HandFinish Hand Finishing Pressure Wash per QSI005 4.3

Memo

0.00

Memo

0.00

Re-alodine tube as per QSI 005 section 4.1.2.1 do not acid etch and leave fwd cap out of solution.

M- 10 08 D()

| Dart Ae | rospace | Ltd | | | | | | | • |
|---------|---------|-------------------|------------------------------|------------------------------|----------------|--------------|--------|-------------------------------------|--------------------------|
| W/O: | | | WC | RK ORDER CHANGE | S | | | | • |
| DATE | STEP | PRO | CEDURE CHAI | NGE | Ву | Date | e Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | ' |
| | | | | | | | | | |
| Part No | | PAR #: | Fault Cate | gory: | NCR: Yes | No DQ | A: | _ Date: _ | |
| | R | esolution: | Disposition: QA: N/C Closed: | | | | Date: | | |
| NCR: | | \ | WORK ORDI | ER NON-CONFORMA | NCE (NCR |) | | | |
| | | Description of NC | | Corrective Action Section | Section B | | cation | Approval | Approval |
| DATE | STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | i i | ion C | Chief Eng | QC Inspector |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DATE | SIEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Section C | Chief Eng | QC Inspector |
|------|------|-----------|----------------------|------------------------------|----------------|-----------|-----------|--------------|
| | | | | | | | | |
| | | · | , | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | 5 | | | | | |
| | | | | | | | | |
| | | | 1 | | | | | |

Work Order ID 60744

Thursday, July 22, 2010 8:17:59 AM



Page 5

Item ID:

D205-634-041

Accept



Setup Start

Stop



Revision ID:

Start Date:

Replacement Skidtube Item Name:

7/21/2010 Start Qty: 1.00

Required Date: 8/6/2010

Req'd Qty: 1.00



Cust Item ID: Customer:

Reference:

| A | | 1 | _ |
|----|-----|------|---|
| AD | pro | vals | : |

QC:

Process Plan:

Date:

Tooling:

SPC (Y/N):

Set Up/

Date: Date:

Tool # Plan

Code

Run

Start

Stop

Reject



Number Stamp

Insp.

Sequence ID/ Work Center ID

180

Powdercoat

Powder Coating

Operation Description

White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum

M115921

Date:_____

Memo

START TIME: OVEN TEMPERATURE:

FINISH TIME:

Run Hours 0.00

11/80/01

Tool ID

Accept

Qty

Reject

Qty

190

QC

Quality Control

QC3- Inspect Part Finish

0.00

0.00

Memo

0.00

M 10 08 12 W

| Dart Ae | rospace | e Ltd | | | | | | | • | |
|----------|---------|-------------------|----------------------|------------------------------|----------------|-------------------|----------------------|-------------------------------------|--------------------------|--|
| W/O: | | | WO | RK ORDER CHANGES | | | | | | |
| DATE | STEP | PR | PROCEDURE CHANGE | | | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| Part No: | | PAR #: | Fault Cate | gory: 1 | NCR: Yes | No DQ | \ : | _ Date: _ | | |
| | R | lesolution: | Disposition | Disposition: QA | | | A: N/C Closed: Date: | | | |
| NCR: | | | WORK ORDE | ER NON-CONFORMAN | CE (NCF | R) . | | | | |
| 5475 | OTED | Description of NC | | Corrective Action Section B | | Verific | ation | Approval | Approval | |
| DATE | STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign 8 Date | ign & Section C | | Chief Eng | QC Inspector | |
| | | | | • | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | ţ | | | | | | |
| | | | | | | | | | | |

| Work | Order | · ID | 60744 |
|-----------|-----------|------|-------|
| ~ ~ ~ ~ ~ | ~ ~ ~ ~ ~ | | ~~. |



Page 6

Insp.

Thursday, July 22, 2010 8:17:59 AM Item ID: D205-634-041 Accept Setup Start **Revision ID:** Stop **Item Name:** Replacement Skidtube **Start Date:** 7/21/2010 Start Qty: 1.00 **Cust Item ID: Req'd Oty:** 1.00 Required Date: 8/6/2010 **Customer:** Reference: Start Run Process Plan: Date:____ **Approvals:** Tooling: Date: Stop Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Accept Reject Reject Work Center ID Description **Run Hours** Code Qty Qty Number Stamp 200 0.00 => III 10/08/12 X(9 HandFinish 0.00 Memo Hand Finishing 1-Install inserts & wearplates & Gaskets as per Dwg. D2580. Use a drop of Sikaflex on insert holes before installing wearplates

A/R □□□ Sikaflex-29 □ ΛΛ 113 □ □ Δ Sikaflex expire date:

2-Coat D2594-3 O' rings with Petroleum Jelly and install on D2594-1 plugs as per Dwg D2580

3-Inspect for foreign object per QSI 024

4-Install 2855 Aft Cap as per Dwg D2580 and seal Fwd Step & Aft Cap with Sikaflex. Clean excess adhesive

A/R □ □□ Sikaflex-291 □ //(// Stips Sikaflex expire date: // 0

5-Wing Walk as per Dwg D2580 and Q 005 4.4 Batch: 115028

Dart Aerospace Ltd

| | • | | | | | | | | |
|-------------|------|-------------------|----------------------|------------------------------|-------------|-------------------|--------|-------------------------------|--------------------------|
| W/O: | | | WORK ORDER CHANGES | | | | | | |
| DATE | STEP | PRO | PROCEDURE CHANGE | | | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | : | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Part No: | | PAR #: | Fault Cat | egory: | _ NCR: Yes | /es No DQA: Date: | | | |
| Resolution: | | | Disposition: QA | | | Closed: | | Date: _ | · |
| NCR: | | V | VORK ORI | DER NON-CONFORMA | ANCE (NC | R) | | · | |
| DATE | STEP | Description of NC | | Corrective Action Secti | | Verifi | cation | Approval | Approval |
| DAIL | J.L. | Section A | Initial Chief Eng | Action Description Chief Eng | Sigr Dat | | ion C | Chief Eng | QC Inspector |
| | | | | | | | | | |
| | | | | | | : | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | · |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | ŀ | | | | İ |
| | | | | | | | | ! | |

Work Order ID 60744

Thursday, July 22, 2010 8:17:59 AM



Page 7

Item ID:

D205-634-041

Accept



Setup Start

Stop



Revision ID:

Item Name:

Replacement Skidtube

Start Date:

7/21/2010

Start Qty: 1.00

Required Date: 8/6/2010

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Process Plan: _____ Date:____

Operation

Description

Date: _____

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Tool ID

Tool # Plan

Code

Date:

Start Run

Reject

Oty

Accept

Oty

Reject

Stop



Number Stamp

Insp.

Sequence ID/

Work Center ID

210

Quality Control

0.00

0.00

Inspect Aft Cap, Fwd Step and Wing Walk of work to Current Step Inspect for

Foreign objects per OSI 024

QC5- Inspect part completeness to step on W/O

20losliz

220



Packaging

Packaging

Packaging

Memo

0.00

0.00

Identify and pack for shipping as per PPPD205-634-041

Location: PPP Rev:

23Ò

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Dart Aerospace Ltd

| W/O: | | WORK ORDER CHANGES | WORK ORDER CHANGES | | | | | | | | | | | |
|---------|------|---------------------------|--------------------|--------|------------|-------------------------------|--------------------------|--|--|--|--|--|--|--|
| DATE | STEP | PROCEDURE CHANGE | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector | | | | | | | |
| | | | : | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| Part No |): | PAR #: Fault Category: NC | R: Yes | No DQA | \ : | Date: _ | | | | | | | | |

| Part No |): | PAR #: | Fault Cate | gory: | NCR: Yes N | lo DQA: | _ Date: _ | Date: | | |
|---------|------|-------------------|--|-----------------------------|----------------|--------------|-----------|--------------|--|--|
| | Reso | olution: | Disposition | Disposition: QA: N/C C | | | Date: _ | | | |
| NCR: | | | WORK ORDE | R NON-CONFORMAN | CE (NCR) | | | | | |
| | | Description of NC | | Corrective Action Section I | 3 | Verification | Approval | I Approval | | |
| DATE | STEP | Section A | Initial Action Description Chief Eng Chief Eng | | Sign & Date | Section C | Chief Eng | QC Inspector | | |
| | | | | | | | | | | |

Picklist Print Work Order ID: 60744 Parent Item:

Thursday, July 22, 2010 8:18:03 AM

D205-634-041

Parent Item Name:

Replacement Skidtube



Start Date: 7/21/2010

Required Date: 8/6/2010

Page 1

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP Rev:N□02.08.28□FP was QC5 in Step 27; Added QC5 to Step 30□KJ

IPP Rev P 10.02.19 per PAR09-043 EC verified by:DD

Manufactured

Manufactured

No

No

IPP Rev. O 06.02.28 Added paperwork EC

IPP Rev:P 07-07-09 SS Wearplates & Gaskets JLM

| Component Item ID/ Item Name | Replacement Item ID | Mfg/ Purch | Bin Item | Primary Location | Last Location | Route Seq ID | Unit of Measure | Qty on Hand | Qty per Kit | Total Qty | Qty Issued | Date Issued | Status |
|-----------------------------------|------------------------|---------------|-------------|---------------------|------------------|-----------------|--------------------|----------------|-------------|--------------|---------------|----------------|----------|
| D2580-1 205 Skidtube bent detail | | Manufactured | No | | | 110 | Each | 6.0000 | 1 | । % ·5? | 913 | MB | 10-07-28 |
| | | | | Location | | Loc | Qty | Loc Code | | | | | |
| | ٠ | | | LG | | | 4 | | | | _ | | |
| | | | | | 57028 | | 1 | | _ | | | | |
| | | | | | 59297 | | 1 . | | | | | • | |

D2576-3

Step (maching detail)

| <u>Location</u> LG | <u>n</u> | Lo | c Oty 90 | Loc Code | | | | n . |
|-----------------------|----------|-----|--------------------|----------|---|---|----------|------------|
| | | 140 | Each | 90.0000 | 1 | 1 | | |
| | 59913 | | 2 | | | | | |
| ST046 | | | 2 | | | | | |
| | 60379 | | 2 | | | - | <u>_</u> | |

D2579

46661 42 52215 48 140 313.0000 Each

Location Loc Qty Loc Code LG 313 57052 5 57348 4 58433 14 59113 290

BE 10/08/04

Crossbolt Spacer

| Dart Ae | rospace | Lta | | | | | | | • |
|-------------|---------|--------------------------------|--------------|--|------------|--------------|----|-------------------------------------|--------------------------|
| W/O: | | | WO | RK ORDER CHANGE | S | | | | , |
| DATE | STEP | PRO | OCEDURE CHAN | CEDURE CHANGE | | | | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | | | | | | |
| : | | | • | | | -1720 | | | |
| | | | | | | | | | · |
| Part No: | | PAR #: | Fault Cate | gory: | NCR: Yes | No DQ | A: | _ Date: _ | |
| Resolution: | | | Disposition | ı: | QA: N/C CI | osed: | | Date: _ | |
| NCR: | | | WORK ORDE | ER NON-CONFORMAN | ICE (NCR | R) | | | |
| DATE | STEP | Description of NC Section A | Initial | Corrective Action Section Action Description | Sign 8 | | | Approval Chief Eng | Approval QC Inspecto |
| | | | Chief Eng | Chief Eng | Date | | | · | |
| | | | | | i i | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | } | | | |

Thursday, July 22, 2010 8:18:03 AM

Work Order ID: 60744

Parent Item:

D205-634-041

Parent Item Name: Replacement Skidtube



Start Date: 7/21/2010

Required Date: 8/6/2010

Start Qty: 1.00

Required Qty: 1.00

D2855

Manufactured No 200


Each


83.0000

Cap

| AN3-5A | Purchased | No |
|--------|-----------|----|









2

| Dolt |
|------|

Bolt

AN960JD10L

| No | |
|----|--|

ST350 105057 115016

Location

Loc Qty 1128 628 500 200 Each Loc Code 3,021.000

10/08/12

Washer

NAS1149D0332J Purchased

Location ST348

(10985

Loc Otv 3021 3021

Loc Code

XZ M 10/08/12

| Dart Ae | rospace | Liu | | | | | | | | |
|-------------|-----------------|--------------------------------|----------------------|------------------------------|------------|-------|---|---|--------------------------|--|
| W/O: | | | WO | RK ORDER CHANGE | ES | | | | | |
| DATE | STEP | PRO | OCEDURE CHAN | IGE | Ву | , E | Date Q | ty Approval Chief Eng / Prod Mgr | Approval QC Inspector | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | 1 | | | | | |
| | | | | | | | | | | |
| Part No | Part No: PAR #: | | Fault Cate | jory: | NCR: Y | es No | Date: _ | Date: | | |
| Resolution: | | | Disposition | n: | QA: N/C | Close | ed: | Date: _ | | |
| NCR: | | 1 | WORK ORDE | R NON-CONFORMA | NCE (N | CR) | | *************************************** | | |
| DATE | OTED | Description of NC Section A | | Corrective Action Section | | | Verification | on Approval | Approvai | |
| DATE | STEP | | Initial Chief Eng | Action Description Chief Eng | ption Sign | | Sign & Section C | | QC Inspector | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | *************************************** | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Thursday, July 22, 2010 8:18:03 AM

| Work Order ID: 60744 Parent Item: D205-634-041 | | | | | 11 | | | | | |
|--|--------------|----|-------------|----------------------------------|--------------|-------------------------------------|-----------------|-------------|---|--|
| Parent Item Name: Replacement Skidtu | be | | | | | | | art Date: 7 | | Required Date: 8/6/2010 Required Qty: 1.00 |
| ALS7-1032-130 | Purchased | No | | | 200 | Each | 950.0000 | 50 | 50 | |
| | | | ST282 | 15079 13238 | <u>L</u> c | 933 933 17 17 | Loc Code | | y | M 10108/17 |
| AN3C4A | Purchased | No | | | 200 | Each | 1,520.000 | 50 | 50 | |
| | | · | 1 1 1 | 14103 14108 14416 14523 | Lo | 1520 501 14 12 2 991 | Loc Code | | - · · · · · · · · · · · · · · · · · · · | M wolosliz |
| AN960C10L NAS1149C0332 | Purchased | No | | | 200 ^^ (\ | Each | 0.0000 | 50 | 50 | M 70108/12 |
| washer D3566-13 | Manufactured | No | • | | 200 | Each | 35.0000 | 1 | 1 | |
| | | | FP012 | 3461) *** 9661 0209 | <u>L</u> . | 4 4 31 23 8 | <u>Loc Code</u> | | _x\ | 10108112 |

Dart Aerospace Ltd

| W/O: | | WORK ORDER CHAN | WORK ORDER CHANGES | | | | | | | | | | |
|---------|------------|------------------------|--------------------|--------------|------------|-------------------------------|--------------------------|--|--|--|--|--|--|
| DATE | STEP | PROCEDURE CHANGE | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector | | | | | | |
| | | | | | | | | | | | | | |
| L | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Part No |) : | PAR #: Fault Category: | NCR: Yes | No DQ | A : | Date: | | | | | | | |

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

| NCR: | | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | | | |
|------|------|--|----------------------|------------------------------|----------------|---------------------------|-----------------------|-------------|--|--|
| | T | Description of NC | | Corrective Action Section B | | | Approval | Approval | | |
| DATE | STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Verification Section C | Approval Chief Eng | QC Inspecto | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | And the second of the second o | | | | | | | | |
| | | | | | | | | • | | |
| | | | | | | į | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Picklist Print

Thursday, July 22, 2010 8:18:03 AM

Page 4

Work Order ID: 60744

Parent Item:

D205-634-041

Parent Item Name: Replacement Skidtube



Start Date: 7/21/2010

Required Date: 8/6/2010

Start Qty: 1.00

Required Qty: 1.00

D3566-5



Manufactured No 200

Each

16.0000

Gasket

Location

FP015

59158

Loc Otv 16

16 200 Each

Loc Qty

21

7 12

Each

Each

Loc Code

21.0000

M 10/08/12

D3566-1

Gasket

Manufactured No

Manufactured

Manufactured

Location FP015

57715

200

200

Loc Code

10.0000

VZ 91 10108/12

D3564-11

Wearshoe

No

No

Location FP019

Location

FP17



Loc Qty 10 10

Loo Oty

19

19

Loc Code 19.0000

1

10/08/17

Loc Code

JU 10/08/12

D3564-13

Wearshoe

Thursday, July 22, 2010 8:18:03 AM

Dart Aerospace Ltd

| W/O: | | | WORK ORDER (| HANGES | | | | 7 |
|---|------------|--------|-----------------|-------------|---------|-----|-------------------------------|--------------------------|
| DATE | STEP | PF | ROCEDURE CHANGE | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | | | | | |
| | | | | | | | | |
| 1900 2000 2000 2000 2000 2000 2000 2000 | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Part No |): | PAR #: | Fault Category: | NCR: Yes | No DQ | A: | Date: _ | |
| | Resolution | n. | Disposition: | 0 A : N/C (| Closed: | | Date: | |

| NCR: | | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | | | |
|------|------|----------------------------------|----------------------|------------------------------|----------------|--------------|-----------|--------------|--|--|
| | | Description of NC | | Corrective Action Section B | | Verification | Approval | Approval | | |
| DATE | STEP | P Description of NC Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Section C | Chief Eng | QC Inspector | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | 1 | | | | |

Picklist Print

Page 5

Thursday, July 22, 2010 8:18:03 AM

Work Order ID: 60744 Parent Item: D205-634-041 Parent Item Name: Replacement Skidtube Start Date: 7/21/2010 Required Date: 8/6/2010 Start Qty: 1.00 Required Qty: 1.00 D3564-9 Manufactured No 200 Each 13.0000 Wearshoe Location Loc Qty Loc Code FP 55334 FP019 12 XI DI 10/08/12 (9201) 12 D3564-5 Manufactured No 200 Each 16.0000 Wearshoe Location Loc Qty Loc Code FG 34806 FP19 57525 58709 FP-19 11 57 (30)01 59157 11 D2594-3 200 Manufactured No Each 443.0000 16 16 O-Ring, 205 Skidtube Location Loc Qty Loc Code 443 55546 19 58191 12 X16W 10/08/12 412

Dart Aerospace Ltd

| W/O: | | | V | ORK ORDER CHANGE | S | · | | | |
|---------|------|-------------------|----------------------|------------------------------|-------------|--------------|--------|---|--------------------------|
| DATE | STEP | PROC | EDURE CH | ANGE | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | | | | | , | |
| | | | | • | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Part No | | PAR #: | Fault Ca | tegory: | NCR: Yes | No DQ | A: | Date: _ | |
| | R | esolution: | Disposit | ion: | QA: N/C C | osed: | | Date: _ | |
| NCR: | | Wo | ORK OR | DER NON-CONFORMA | NCE (NCF | R) . | | | |
| DATE | STEP | Description of NC | | Corrective Action Section | | Verifi | cation | Approval | Approval |
| DAIE | SIEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | k Sec | tion C | Chief Eng | QC Inspector |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | ļ | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | 10-14-17-0 | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Picklist Print

Thursday, July 22, 2010 8:18:03 AM

Page 6

Work Order ID: 60744

Parent Item:

D205-634-041

Parent Item Name: Replacement Skidtube



Start Date: 7/21/2010

Required Date: 8/6/2010

Start Qty: 1.00

Required Qty: 1.00

D2594-1

Plug, 205 Skidtube

Manufactured

200

Each 451.0000

16 16

| Location | Loc Oty | Loc Code | | |
|----------|---------|----------|-------|----------|
| FP | 183 | | | |
| 42807 | 112 | | | |
| 55002 | 71 | | | |
| FP14 | 268 | | | 1 |
| (58434) | 79 | | 16 90 | 10/08/12 |
| 59110 | 189 | | | (9100112 |

| rospace Lt | d | | | | | | | |
|------------|---|---|---|--|---|---|---|---|
| | | WC | ORK ORDER CHANG | ES | | | | |
| STEP | PROCEDURE CHANGE | | | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | *************************************** | | | | | | | |
| | | | | | | | | |
| | | WORK ORD | ER NON-CONFORM | ANCE (NC | ₹) | | | |
| STEP | Description of NC Section A | Initial Chief Eng | Corrective Action Sec Action Description Chief Eng | Sign | & Sec | | Approval Chief Eng | Approval QC inspector |
| | | | | | | | | |
| | STEP Resc | :PAR #: Resolution: STED Description of NC | STEP PROCEDURE CHA : PAR #: Fault Cate Resolution: Dispositio WORK ORD STEP Description of NC Section A Initial | STEP PROCEDURE CHANGE :PAR #:Fault Category: Resolution:Disposition: WORK ORDER NON-CONFORM STEP Description of NC Section A Section A Section A Section A Section A Section A Section Description Section A Secti | WORK ORDER CHANGES STEP PROCEDURE CHANGE By :PAR #:Fault Category:NCR: Yes Resolution:Disposition:QA: N/C C WORK ORDER NON-CONFORMANCE (NCI STEP Description of NC | WORK ORDER CHANGES STEP PROCEDURE CHANGE By Date :PAR #:Fault Category:NCR: Yes No DC Resolution:Disposition:QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC | WORK ORDER CHANGES STEP PROCEDURE CHANGE By Date Qty :PAR #:Fault Category:NCR: Yes No DQA: Resolution:Disposition:QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC | WORK ORDER CHANGES STEP PROCEDURE CHANGE By Date Qty Chief Eng / Prod Mgr :PAR #:Fault Category:NCR: Yes No DQA:Date: |



| DESIG | * ## | DRAWN BY | DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA |
|-------|--|----------|--|
| CHECI | KED. | APPROVED | DRAWING NO. REV. LD |
| | The state of the s | | D2580 SHEET 1 OF 3 |
| DATE | | | TITLE SCALE |
| 07.0 | 2.27 | | 205 SKIDTUBE ASSEMBLY NTS |
| Α | | 96.09.16 | NEW ISSUE |
| В | | 96.12.02 | AS MANUFACTURED |
| C | | 98.08.26 | REDRAWN, INCLUDED DEO 9094/9097 |
| D | | 07.02.27 | CHANGE TO SS WEARPLATES AND GASKETS, INCLUDE DEO 9124/9183 |

RETURN TO ROPT ENGINEERING COPT



| QTY -041 | QTY -045 | Part Number | Description |
|-------------|-------------|------------------|-------------------|
| X | -043 | D2580-041 | SKIDTUBE ASSEMBLY |
| | X | D2580-045 | SKIDTUBE ASSEMBLY |
| | | | - |
| 1 | 1 | D2500-1-190 | EXTRUSION |
| 1 | 1 | D2576-3 | STEP |
| 20 | 24 | D2579 | CROSS BOLT SPACER |
| 16 | 16 | D2594-1 | PLUG |
| 16 | 16 | D2594-3 | O-RING |
| 1 | 1 | D2596 | 205 WEB |
| 1 | 1 | D2855 | AFT CAP |
| 1 | 1 | D3564-5 | WEARSHOE |
| 1 | 1 | D3564-9 | WEARSHOE |
| 1 | 1 | D3564-11 | WEARSHOE |
| 1 | 1 | D3564-13 | WEARSHOE |
| 2 | 2 | D3566-1 | GASKET |
| 1 | 1 | D3566-5 | GASKET |
| 1 | 1 | D3566-13 | GASKET |
| | | | |
| 50 | 50 | ALS7-1032-130 | INSERT |
| | | or AKS7-1032-130 | |
| | | or AKS4-1032-130 | |
| | | or AELS-1032-130 | · |
| 50 | 50 | AN3C4A | BOLT |
| 2 | 22 | AN3-5A | BOLT |
| 50 | 50 | AN960C10L | WASHER |
| 2 | 2 | AN960JD10L | WASHER |

GENERAL NOTES:

- 1) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 2) ALL DIMENSIONS ARE IN INCHES
- 3) INSERT D2596 WEB TO LOCATION SHOWN OFF AFT END OF SKIDTUBE AND BOND WEB INTO OUTER TUBE WITH NON-STRUCTURAL SIKAFLEX-241 ADHESIVE PER DART QSI 015 BEFORE BENDING. ENSURE HOLES LINE-UP.
- 4) BEND AS A SMOOTH RADIUS STARTING WITH A MAXIMUM CENTERLINE RADIUS OF 60 AND ENDING WITH A MINIMUM RADIUS OF 30. A MAXIMUM REDUCTION OF 0.200 IN DIAMETER IS ALLOWABLE IN THE BENT PORTION OF THE TUBE.
- 5) USE DART DRILL TEMPLATE TD2577-205 TO LOCATE AND DRILL Ø0.297 HOLES FOR WEARSHOE INSERTS. INSTALL ALS7-1032-130 PER SECTION D-D (50 PLACES) AFTER FINISH. INSTALL AN3C4A BOLTS AND AN960C10L WASHERS WITH SIKAFLEX-241/-291.
- 6) WELDING TO BE DONE PER DART QSI 004.
- 7) FINISH:

SEE NOTES ON

PAGE 2 FOR D2580-041 AND


PAGE 3 FOR D2580-045

 INSERT D2594-1 PLUG C/W D2594-3 O-RING IN HOLES MARKED 'P' (BOTH SIDES OF TUBE) AFTER FINISH (16 PLACES).

Copyright @ 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.


| Dart Ae | rospace | e Ltd | | | | | | | | 4 |
|---------|---------|--------------------------------|------------------|----------------------------------|-----------|------------|--------------|-----------------|-------------------------------|--------------------------|
| W/O: | | | WO | RK ORDER CH | ANGES | | | | | |
| DATE | STEP | PRO | PROCEDURE CHANGE | | | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | | | | | | , | |
| | | | | | | | | | | |
| Part No | | PAR #: | Fault Categ | ory: | NCF | : Yes I | No DQ | A: | Date: | |
| | | esolution: | | | | | | | | |
| NCR: | | \ | WORK ORDE | R NON-CONFO | RMANCE | (NCR) |) | | | |
| DATE | STEP | Description of NC Section A | Initial | Corrective Action Action Descrip | Section B | Sign & | 1 | cation ion C | Approval Chief Eng | Approval QC Inspector |
| | | | Chief Eng | Chief Eng | | Date | | | | |
| | | | | | | | | | | : |
| | | | | | | 111_0, 121 | | | | |
| | | | | | | | | | | |



| Dart Ae | rospace | Lia | | | | | | • |
|---------|---------|------------|--------------------|-------------|-----------|-----|-------------------------------------|--------------------------|
| W/O: | | | WORK ORDER (| CHANGES | | | | •, |
| DATE | STEP | | PROCEDURE CHANGE | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | : | | | |
| | | | | | | | | |
| Part No |): | PAR #: _ | Fault Category: | NCR: Y | es No DC | A: | Date: _ | |
| | R | esolution: | Disposition: | QA: N/0 | Closed: _ | | Date: _ | |
| | | | WORK OPDED NON-COM | EODMANCE (N | CD) | | · · · · · · | |

| NCR: | | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | | | |
|------|------|----------------------------------|----------------------|------------------------------|----------------|--------------|-----------|--------------|--|--|
| | | Description of NC | | Corrective Action Section B | | Verification | Approval | Approval | | |
| DATE | STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Section C | Chief Eng | QC Inspector | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

W6 45744



| Dart Aerospace L | .ta |
|------------------|-----|
|------------------|-----|

| W/O: | | WORK ORDER CHANGES | | | | | | |
|-----------|--|--------------------|--|------|-----|-------------------------------------|--------------------------|--|
| DATE STEP | | PROCEDURE CHANGE | | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC inspector | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| Part No: | PAR #: | Fault Category: | NCR: Yes No DQA: | Date: |
|----------|-------------|-----------------|------------------|-------|
| | Resolution: | Disposition: | QA: N/C Closed: | Date: |

| NCR: | | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | |
|------|------|----------------------------------|-----------------------------|------------------------------|----------------|--------------|-----------------------|--------------------------|
| | STEP | Description of NC | Corrective Action Section B | | | Verification | Annessal | Approval |
| DATE | | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Section C | Approval Chief Eng | Approval QC Inspector |
| | | w. | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | 11 | |
| | | | ļ | | | | | ,0 |
| | | | | | | | | |
| | | | i t | | | | | |
| | | | | | | | | |

NO. <u>333</u>

AWS D17.1.2001 QUALIFICATION TEST RECORD

| Name: Baclay Elliott |
|------------------------------|
| Job number: 59105 |
| Part number: D205-634-041 |
| Description: 305 skid tube |
| Welding Process: Tig[Mig[] |
| Base materiel: Aluminian |
| Current: AC[/] DC[] |

TEST REQUIREMENTS AND RESULTS

| Visual: Penetration: | pass[] fail[] pass[] fail[] |
|--|--|
| UNACCEPTABLE | |
| Cracks: Undercut: Pin holes: Overlap (cold lap) Porosity (surface): Coloration: | pass[/] fail[] pass[/] fail[] pass[/] fail[] pass[/] fail[] pass[/] fail[] |
| Qualifier Las Dun. Welder Booklay Welcor | Date of Test Coupon 10.06.01 Date of Test Coupon 10.06.01 |

The above named individual is qualified in accordance with AWS D17.1.2001 to weld